

32-E-104AB

1
A2
2 : ()
() 5
≥ 1600mm
3


1 AES
-1700-3.75/4.87-835-6/ 2
19-4I

2				4	

2 GB/T151-2014 I
3 16Mn NB/T 47008-2008
4 GB9948-2013
5 2
X
1% NB/T47013 II
6 HG/T 20583-2011
7
8
9 JB/T4673-2003
10
11
12 () SHY-99

1%





- 技术要求:
1. 本壳体的直线度偏差不得大于2mm。
 2. 法兰螺栓孔应跨中装配。
 3. 筒体同一截面上最大内径与最小内径之差不应大于筒体内径的0.5%，且其值不大于2mm。
 4. 壳体内表面焊缝余高均应磨平。

其余

